

# TOSHIBA QUICK TIPS

## “Meter Reading for Non-Color Copiers”

1. Press the [COUNTER] button on the control panel to access the COUNTER menu.
2. Press [TOTAL COUNTER].
  - a) The TOTAL COUNTER screen is displayed.
3. Press [PRINT COUNTER].
  - a) The PRINT COUNTER screen is displayed.
4. Select [TOTAL]
  - a) Provide the TOTAL number listed under BLACK

